

Mr. Carl Holley
VP, Safety, Health & Environmental Security & Regulatory Compliance
Intercontinental Terminals Company, LLC
1943 Independence Parkway South
Deer Park, TX 77536

Re: EPA Onsite Infrared Camera Survey Videos

Dear Mr. Holley:

Included in this package please find a DVD-R with the infrared videos (MOV_0111 through MOV_0116) that were recorded during our May 1, 2013, site visit at your facility. MOV_0111 shows emissions from vents on Tank 80-9 which contained No. 6 Oil; MOV_0112 shows emissions from vents on Tank 80-12 which also contained No. 6 Oil; MOV_0113 shows emissions from vents on Tank 80-15 which contained pygas; MOV_0114 shows emissions from vents on Tank 80-7 which also contained pygas; MOV_0115 shows emissions from vents on Tank 80-9 (from a different angle than MOV_0111); and MOV_0116 shows emissions from vents on Tank 80-2 which contained ethyl alcohol (ethanol).

Should you have any questions or have any issues viewing the videos, please feel free to contact me at [[HYPERLINK "mailto:valentine.greg@epa.gov"](mailto:valentine.greg@epa.gov)] or (214) 665-3111.

Thanks for your assistance while we were onsite,

Greg Valentine
Enforcement Officer